



AUTOMOBIL- UND MOTOREN-WERKE  
BREMEN - GERMANY

**Location of front  
flexible brake hose  
"Isabella"**

**B**  
**204**

Bremen, Germany, April 18th, 1957

To all  
Authorized Borgward Dealers and Workshops

Gentlemen:

We have previously indicated in several Service Bulletins that the location of the front brake hoses is made according to precise instructions. In this connection we have mentioned that the perfect condition of the flexible brake hoses and their attachment must be checked on all vehicles.

We had to ascertain, however, that the essential attention was not always paid to this matter and it is thus necessary to indicate again the importance of these controls. Will you therefore please take due notice that aside from the extent of work which is determined in the maintenance services I and II (Pos. 33 of the maintenance service) the brake hoses must be checked on every ensuing occasion. Every vehicle which is brought into your Workshop is subject to these controls, independent of the kind of work which is carried out on the vehicle.

When accomplishing these controls two types of locations of the flexible brake hoses must be taken into account:

Up to Chassis No. 1 102 037 (234 472) instructions according to previous Service Bulletins are in force.

From Chassis No. 1 102 038 (234 473) the location of the flexible brake hoses has been altered. In the case of this type a suitable fastening plate with clip is now attached to the axle girder instead of the previously fitted holder on the stubaxle.

We therefore wish to draw your attention to the importance of the flexible brake hose within the brake system, it is therefore self-evident that this type too must undergo a constant control in above mentioned sense.

Yours very truly,  
**CARL F. W. BORGWARD G. M. B. H.**  
KUNDENDIENST  
(CUSTOMERS SERVICE)  
DEPT.

signed Grimberg

signed Wolff